

CHSNE ONE ARRIVAL (RNAV)

ARRIVAL ROUTE DESCRIPTION

HRTUN TRANSITION (HRTUN.CHSNE1)KISTS TRANSITION (KISTS.CHSNE1)LOPPY TRANSITION (LOPPY.CHSNE1)MEMPHIS TRANSITION (MEM.CHSNE1)TINCA TRANSITION (TINCA.CHSNE1)

From over CHSNE on track 069° to BAWLS, cross BAWLS at/above 10000, then on track 069° to JATGO, then on track 069° to OLNAH, thence on assigned runway transition.

LANDING RWYS 2L/2C/2R: From over OLNAH on track 086° to TUPIE, cross TUPIE at 4000. Expect RNAV (RNP) approach.

LANDING RWYS 20L/20C/20R: From over OLNAH on track 066° to NUVOO, cross NUVOO at/above 6000, then on track 021° to JOGLO, cross JOGLO at 5000, then on track 021°. Expect radar vectors to final approach course.

LANDING RWY 13: From over OLNAH on track 052° to PINSE, cross PINSE at 4000, then on track 052°. Expect radar vectors to final approach course.

LANDING RWY 31: From over OLNAH on track 085° to MLANI, cross MLANI at/above 6000, then on track 085° to BGEDD, cross BGEDD at 4000, then on track 085° to RUNEE, then on track 136° to IDOBE, then on track 136°. Expect radar vectors to final approach course.

SE-1, 07 FEB 2013 to 07 MAR 2013

SE-1, 07 FEB 2013 to 07 MAR 2013