

### ARRIVAL DESCRIPTION

HECTOR TRANSITION (HEC.BASET3): From over HEC VORTAC via HEC R-211 and PDZ R-030 to CIVET INT, then via LAX R-068 to BASET INT. Thence....

PEACH SPRINGS TRANSITION (PGS.BASET3): From over PGS VORTAC via PGS R-229 and PDZ R-046 to RUSTT INT, then via LAX R-068 to BASET INT. Thence....

TWENTYNINE PALMS TRANSITION (TNP.BASET3): From over TNP VORTAC via TNP R-245 and PDZ R-069 to PDZ VORTAC, then via PDZ R-265 to BASET INT. Thence....

.... From over BASET INT/DME via LAX R-068 to cross DOWNE INT/DME at or above 10,000' and cross REEDR INT/DME at or above 9,000'. Depart REEDR via heading 210° for radar vectors to final approach course for Runways 6L/R or 7L/R.

LOST COMMUNICATIONS: Depart REEDR heading 210° to intercept the SLI R-251 to TANDY INT/SLI 30 DME.

SW-3, 07 FEB 2013 to 07 MAR 2013

SW-3, 07 FEB 2013 to 07 MAR 2013